




Magnetic Lock

wiring diagram
DC 24V



Downee

KEY AUTOMATION CONTROL BOARD



Gel
Joiner

Adaptor



CUT OFF OUTPUT CONNECTOR
AND STRIP WIRES.



POSITIVE CABLE IS MARKED
WITH GREY STRIPES

WARNING

CONNECTING THE POLARITY
WRONG WILL DAMAGE SURGE
SUPPRESSION UNIT AND ISN'T
COVERED IN WARRANTY.